



Make **Toyota**

Model	Year	Chassis	Engine	Trim	Section	Replacement Diff	Standard Metal Spec II			Carbon LSD Spec II			Carbon LSD Spec III, Spec IV			
							Parts number	Retail price	Note	Parts number	Retail price	Note	Parts number	Retail price	Note	
MarkII Chaser Cressida	84.8-88.8	GX71	1G-GE	MT, AT	R	OP	A: 2 way, B: 1.5 way, C: 1 way, D: 1.8 way			CTRA(B)95H10	¥166,000	#2				
					VI	CTRA(B)95H10				¥166,000	#2, #5					
			1G-GTE	MT, AT	R	OP				CTRA(B)109H11	¥166,000					
	88.8-	GX81	1G-GE	MT	R	OP				CTRA(B)95H10	¥166,000					
				AT	R	OP				CTRA(B)109H11	¥166,000	#10				
			1G-GTE	MT	R	OP				CTRA(B)109H11	¥166,000	#4				
					R	VI				CTRA(B)109H11	¥166,000					
				AT	R	OP				CTRA(B)109H11	¥166,000					
		1G-GZE	MT	R	OP				CTRA(B)109H11	¥166,000	#4					
	90.8-92.1	JZX81	1JZ-GE	MT, AT	R	OP				CTRA(B)109H11	¥166,000	#4				
			1JZ-GTE	MT, AT	R	OP				CTRA(B)109H11	¥166,000	#11				
	92.10-96.8	JZX90	1JZ-GE	MT, AT	R	OP				CTRA(B)95H10	¥166,000					
			1JZ-GTE	MT	R	OP/TO				CTRA(B)109H11	¥166,000	#6				
				AT	R	OP				CTRA(B)109H11	¥166,000					
					R	TO			CTRA(B)109H11	¥166,000	#6					
	92.10-96.8	JZX91	2JZ-GE	MT, AT	R	OP/TO				CTRA(B)109H11	¥166,000	#6				
	96.9-00.10	JZX100/105	1JZ-GE	MT, AT (No 5AT)	R	OP				CTRA(B)95H10	¥166,000					
	96.9-97.8	JZX100	1JZ-GE/GTE	5AT	R	OP				CTRA(B)10911	¥166,000	#6				
	97.8-	JZX100	1JZ-GE/GTE	5AT	R	OP				CTRA(B)109H11	¥166,000	#10				
			1JZ-GTE	MT, 4AT	R	OP				CTRA(B)109H11	¥166,000					
				R	TO				CTRA(B)109H11	¥166,000	#6					
		JZX101	1JZ-GTE	MT, AT	R	OP				CTRA(B)109H11	¥166,000	#6				
	96.9-97.8	JZX101	1JZ-GE/GTE 2JZ-GE	5AT	R	OP				CTRA(B)109H11	¥166,000	#6				
	97.8-00.1	JZX101	2JZ-GE	5AT	R	OP				CTRA(B)109H11	¥166,000	#10				
	00.1-04.11	JZX101	1JZ-GTE	MT, AT	R	TO				CTRA(B)109H11	¥166,000	#6				
					R	OP				CTRA(B)109H11	¥166,000	#10				
	96.9-	GX100	1G-FE	MT, AT	R	OP				CTRA(B)95H10	¥166,000					

Note

#2: Bearing 90368-50006 x2 are required

#4: Side shaft 41309-14060 x2 are required (or the stock shaft could be modified)

#5: Side shaft 41309-22012 x2 are required

#6: For a vehicle equipped with the stock torsen LSD, side shaft 41309-22050 x2 are required

#10: A modification to the stock shaft (6mm machining) is required

#11: The LSD can also replace the stock Toyota LSD